

Submission number **2025\_98300**  
ID **28857**

## 1 | Countries concerned

Countries concerned *	<b>Austria</b>	<b>Belgium</b>	<b>Bulgaria</b>	<b>Czechia</b>
	<b>Germany</b>	<b>Estonia</b>	<b>Spain</b>	<b>France</b>
	<b>Greece</b>	<b>Croatia</b>	<b>Hungary</b>	<b>Ireland</b>
	<b>Italy</b>	<b>Lithuania</b>	<b>Latvia</b>	<b>Malta</b>
	<b>The Netherlands</b>	<b>Poland</b>	<b>Portugal</b>	<b>Romania</b>
	<b>Slovenia</b>	<b>Slovakia</b>		
	Main Member State *	<b>France</b>		

## 2 | Economic operator or provider of online marketplaces submitting the notification

The manufacturer \* **Is the Notifier**

Name or identification of the manufacturer \* **DECATHLON SE**

Responsibility

Contact name \* **CORALIE GLEDEL**

Address \* **4 BOULEVARD DE MONS**

Town/City \* **VILLENEUVE D'ASCQ**

Postal code \* **59650**

Country \* **France**

Electronic address \* **coralie.gledel@decathlon.com**

Telephone \* **+33625126268**

Website

Type \* - Manufacturer of the product  
- Distributor of the product

### 3 | Product involved

Category \* **Hobby/sports equipment**

Sub-category **Basketball hoop**

Brand \* **TARMAK**

Type/number of model **4239136**

Bar code

Total number of affected products circulating on the single market

Custom code

Country of origin \* **Portugal**

Brief description \* **A basketball hoop B900 BOX NBA**

Detailed description **No file(s) attached**

Photo [\\_image \(2\).jpg](#)

### 4 | Description of the accident or of the safety issue

#### Description of the accident

What was the consequence of the accident?

**Injury**

Please specify what injury did the person sustain

**Injuries**

What treatment did the person receive?

**Emergency Department / Hospital admission**

Describe the accident in detail, including any injury involved and how the product(s) was used. This information will help process your case

**A child had his hand on the post when the hoop fell on his finger.**

When did the accident happen?

Age of the affected person (in years)

## 5 | Risk assessment of the notifier

Description *	<b>If the red height crank handle is removed while the product is being used or handled, the post may fall vertically. This can lead to potential hand injuries.</b>
Level of risk *	<b>Serious</b>
Report document	<b>No file(s) attached</b>

## 6 | Corrective actions already taken or planned

Action *	<b>Recall of the product from end users</b>
Please specify	<b>Consumers will carry themselves a security solution using a repair kit that Decathlon will provide.</b>
Scope of the actions *	<b>EEA wide</b>
Duration of the actions *	<b>Permanent</b>
Results of the actions	
Company taking action	

---

Additional information and information meant to alert consumers as referred in Article 9(9) of the GPSR (see user manual for detailed guidance)

## 7 | Company(ies) in the supply chain which hold affected products

Details of the COMPANY (IES)	<b>No file(s) attached</b>
------------------------------	----------------------------

## 8 | Other

Language	<b>No file(s) attached</b>
----------	----------------------------